

Zeitschrift: Swiss express : the Swiss Railways Society journal
Herausgeber: Swiss Railways Society
Band: - (2015)
Heft: 124

Artikel: Sometimes not up to the usual standard! : Phil Weaver suffers a locomotive failure on the MGB
Autor: Weaver, Phil
DOI: <https://doi.org/10.5169/seals-854004>

Nutzungsbedingungen

Die ETH-Bibliothek ist die Anbieterin der digitalisierten Zeitschriften auf E-Periodica. Sie besitzt keine Urheberrechte an den Zeitschriften und ist nicht verantwortlich für deren Inhalte. Die Rechte liegen in der Regel bei den Herausgebern beziehungsweise den externen Rechteinhabern. Das Veröffentlichen von Bildern in Print- und Online-Publikationen sowie auf Social Media-Kanälen oder Webseiten ist nur mit vorheriger Genehmigung der Rechteinhaber erlaubt. [Mehr erfahren](#)

Conditions d'utilisation

L'ETH Library est le fournisseur des revues numérisées. Elle ne détient aucun droit d'auteur sur les revues et n'est pas responsable de leur contenu. En règle générale, les droits sont détenus par les éditeurs ou les détenteurs de droits externes. La reproduction d'images dans des publications imprimées ou en ligne ainsi que sur des canaux de médias sociaux ou des sites web n'est autorisée qu'avec l'accord préalable des détenteurs des droits. [En savoir plus](#)

Terms of use

The ETH Library is the provider of the digitised journals. It does not own any copyrights to the journals and is not responsible for their content. The rights usually lie with the publishers or the external rights holders. Publishing images in print and online publications, as well as on social media channels or websites, is only permitted with the prior consent of the rights holders. [Find out more](#)

Download PDF: 01.07.2025

ETH-Bibliothek Zürich, E-Periodica, <https://www.e-periodica.ch>

Sometimes not up to the usual standard!




MGB HGe 4/4 No. 106 waiting at Tschamut-Selva to be rescued, with the guard looking on.

Photos: Phil

Phil Weaver suffers a locomotive failure on the MGB

Last summer a friend and I enjoyed a great two-week Swiss holiday, primarily to 'do' the Gotthard Route during the final year of its present incarnation and for this we based ourselves in Goschenen, as it was central to everything we wanted to do. It also meant that we could have a few 'days off' to travel on other lines. On one such day, having never travelled on the RhB, we decided to go to Filisur to enjoy the famous railway infrastructure en-route. Everything went well until the return trip home. The locomotive hauling our train was MGB HGe 4/4 No.106 and just after we had passed Tschamut-Selva, and were within a couple of hundred metres of the avalanche shelter, we came to a very sudden stop. After about ten or fifteen minutes of trying to restart on the hill, the train began to go backwards down the hill (this is when you hope the rack and pinion works) and returned to Tschamut-Selva. The guard came through and told us that the locomotive had a problem and wouldn't be able to continue, as it appeared to have lost power in two of its motors. It apparently had become a HGe 2/4! He asked where we were going and as we were going to Goschenen he told us to stay on the train. He said other passengers would catch the train going the other way that had been held at Oberalp Pass and was now running about ten minutes late. As our train had extra carriages on, in the form of an open coach and a vintage coach, we were actually too long for the loops at Tschamut-Selva. This meant we had to set back to let the eastbound train enter and then shunt forward to let it out. About five or six other passengers had caught the other train, leaving us to find out that we were the only ones left, so we had the train to ourselves with two train crew. At about 17:30, some 40 minutes after we had failed, another locomotive

arrived in the shape of HGe 4/4 No.104 that had been sent from Disentis to rescue us. There now followed another couple of shunts back and forward, so that our locomotive could be removed and the new locomotive could be attached to our train. So, just 50 minutes after we broke down we were on our way again. Swiss efficiency, Britain take note. Also we were not locked in the train while this was all going on, but were free to get off and move around quite freely. Unfortunately our adventure was not quite over yet. As we were approaching Oberalp Pass the guard came to us and said that the train would terminate at Oberalp Pass and we would have to catch the following train, as obviously running to Andermatt with just two passengers would not be economical. As our train was scheduled to terminate at Andermatt to return to Disentis, reversing at Oberalp Pass made more sense, as it would also enable it to get its booked path back. Of course when the engine ran round, it also had to shunt back to let the following train get into the station. This service was now running about ten minutes late and the new guard told us we would probably not make the 18:28 service from Andermatt to Goschenen - and he was proved to be correct. As we pulled in to Andermatt our connection pulled out, so it was obviously not a guaranteed connection. The beer in the station buffet went down very well though! 

The two locomotives swapping over.

